106.1N.0008

20117 Instrument Reception And Incoming Inspection Checklist, scanned 2009.01.13 Rev A - Pre-release ESD control measures exception: Identification and Shipping Documentation 3.3.1 Biospherical Instruments Inc Manufacturer: Vendor (If Different): QSP 2150 Model Number: 50115 Serial Number: Sally Leys Principal Investigator: Purchasing Agent (If Different): FOLGER PASSAGE PINNACLE. Target Deployment Site: Shipping Damage 3.3.2 Describe any evidence of damage or tampering in shipping or handling. Append digital images where appropriate. * Packaging is at variance of spec but intact and unmarked. Photos on file. Completeness of Shipment 3.3.3 Note any missing material or other deviation from the packing list. * Shipment matches packing list-complete Conformance with Requirements 3.3.4 Indicate compliance with the following requirements: Yes No k warming in Package marked ESD sensitive? Yes ☐ No 🔀 Fail 🗌 Purpose-built, reusable shipping enclosure? Yes No X Fail Instrument fixed in position (no loose packing)? Yes 🗌 No 🔀 Package marked with shock constraint? Yes 🗌 No 🔀 Fail 📗 Shock recording device enclosed? Yes 🗌 No 🔀 Fail 🗌 Allowable shock limit exceeded? *

Connectors covered and protected?

bulkhear covered, intime on cable

Yes 🛛 No 🔀 Fail 🗌

Fibre-optic cables constrained as to bend radius?	ري Yes ☐ No ☐ Fail ☐
Electrical cables constrained as to bend radius?	Yes ☑ No ☐ Fail ☐
External visual inspection of seals acceptable?	Yes ☑ No ☐ Fail ☐
External visual inspection of closing acceptable?	Yes ☑ No ☐ Fail ☐
Visual inspection of cable moulding acceptable?	Yes ☑ No ☐ Fail ☐
Operation Manual supplied?	Yes ☑ No ☐ Fail ☐
Deployment and recovery instructions supplied?	Yes ☐ No ☑ Fail ☐
Maintenance instructions supplied?	Yes ☑ No ☐ Fail ☐
Quality Plan submitted?	Yes ☐ No ☑ Fail ☐
Qualification plan required/ submitted?	Yes ☐ No ☑ Fail ☐
Software development plan required/ submitted?	Yes ☐ No ☑ Fail ☐
Test Plan submitted?	Yes ☑ No ☐ Fail ☐
checkout procedure in manual	
List of appended items (images, notes, etc)	
Sermany: perskagery, convertor cover, deployment & navery instructions et variable - acceptable. Asking for	
deploquent & skowery instructions of	
vacionel - auchtable. Asking for	
processive test configurate	
Completion noted in log (DMAS)	
2007. (2: (/ (yyyy.mm.dd) date	
signature Zefallee	

^{*} Report immediately to the NEPTUNE Canada office.